


1. The method of packaging and dimension are shown as below figure. (Dimension in mm)



2. Label

2.1 The information of inner box label must be listed: (Description of a sample label)

2.1.1	TYPE LL4148	means (Product) TYPE (Part No.)
2.1.2	QTY 20000 PCS	means (Product) Quantity (QTY)
2.1.3	D/C SLB6J0908S	means Dice Lot No. / Code (D/C)
2.1.4	P/C MFJJ0344	means Production Code (P/C)
2.1.5	RMK 110806	means Manufacturing Date (RMK)

2.2 The information of carton label must be listed:

- 2.2.1 TYPE
- 2.2.2 QTY